

BUILDING SAFETY CERTIFICATE

NO. 3323

Dated 2 JUL 2026

It is certified that the existing building **ST. Joseph School**, (Name of the building or premises) at **Opp. Mahada Colony, Pitesur road, Godhani, Nagpur** (address) is having block (s)/Floor(s) as per details below:


Details of Block (s) in School	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor (s) in the block	G + 3					

The Building is owned/occupied by **ST. Joseph School, Opp. Mahada Colony, Pitesur road, Godhani, Nagpur** (Name of the Institution) have complied with the Building Safety requirements in accordance with National Building code Rules, and verified by the officers concerned of **R.K. Karandikar, Structural & Chartered Engineer from consulting Nagpur** & the officers concerned of Sub-Division Engineer, Nagpur (Rural) Also visited the side on date **22/06/2026** (Date of Inspection) in the presence of **Edward Rajesh Francis (Admin Officer)** (Name and addresses of the Manager / Secretary or his representative) and that the building / premises is fit for occupancy for running school with effect from **2026 - 27** for a period of **1 (One)** years in accordance with rule and subject to compliance of the specific conditions as appended.

1. Structural stability should be examined also with reference to location, altitude, intensity of wind floor.
2. Fire safety inspection / report should be done by agency separately

Issued on _____ at Nagpur by.

- Stick out whichever is not applicable. In case of block is more than six use separate sheet for detail.


Sub Divisional Engineer
Public Works Sub Division
(Rural) Nagpur.

Signature with Seal

Name :

Designation :

Name & Address of Department/ Office:


Executive Engineer
Public Works Division 2
Nagpur